Form No. LSB-OOS-4 May 1969

Form Approved Budget Bureau No. 44-R1387 Approval Expires April 30, 1971



## MATERIAL SAFETY DATA SHEET

SEC	TION I	
MANUFACTURER'S NAME DOW CORNING CORPORATION		EMERGENCY TELEPHONE NO. (517) 636-8393
ADDRESS (Number, Street, City, State, and ZIP Code) South Saginaw Rd., Midland, Michigan	48640	
CHEMICAL NAME AND SYNONYMS	· · <del>-</del> ·	TRADE NAME AND SYNONYMS DOW CORNING® 1200 RTV prime:
CHEMICAL FAMILY	FORMULA	A

PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS			BASE METAL		
CATALYST			ALLOYS		
VEHICLE			METALLIC COATINGS		
SOLVENTS			FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS		
OTHERS					
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES					TLV (Units)
VM and P Naphtha				80	100
					ppm

BOILING POINT (F.)	Approx.	210°F	SPECIFIC GRAVITY (H <sub>2</sub> 0=1)	Approx.	0.9
VAPOR PRESSURE (mm Hg.)	Approx.	25 mm	PERCENT VOLATILE BY VOLUME (%)		<5%
VAPOR DENSITY (AIR=1)		>1	EVAPORATION RATE		NA
SOLUBILITY IN WATER		<0.1%			_
APPEARANCE AND ODOR	Liquid -	solvent	odor		
			and the second s		

BON 이번째 프로틴 이 그리고 있다면 하는 사람들은 바로 모든 사람들이 되었다.		
Open Cup Approx. 50°F FLAMMABLE LIMITS	1.2	0el
extinguishing media CO2 or foam	-	
SPECIAL FIRE FIGHTING PROCEDURES None		
UNUSUAL FIRE AND EXPLOSION HAZARDS NONE		
		:
		A 10 St 10 S

	سنحمص								
			ECTIO	ŴŶ ł	HEAL	TH HAZARD DA	NTA SECURE OF SECURITION OF SE		
THRESHOLD LIMIT VA	LUE	100	ppm	_					
EFFECTS OF OVEREXPO	DSURE	May	caus	- e sli	.ght	anesthesi	a, headaches, etc.		
·									
EMERGENCY AND FIRS	ST AID	PROCEDURES	In	halat	ior	remove	to fresh air.		
Obta:	in m	edical &				-	res - flush with water.		
V		<u> </u>	1000	<u> </u>		January			
2742-28-54-20-0	g et eks	( A) ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( ( (		SECTION S	i and	V (6 7 2 9 3 C + 15 x 2 7 2 )			
	4.50	2	SECT	ON VI	RI	EACTIVITY DATA			
STABILITY	UNST	TABLE		CONDI	TION	S TO AVOID			
	STAB	3LE	Х						
INCOMPATABILITY (Me	aterial:	s to avoid)		ne kn	יראזרי	<u> </u>			
HAZARDOUS DECOMP						No.	ely burned carbon products		
	.UED	MAY OCCUR	<u>10 01.</u>	1000_	<u></u>	CONDITIONS TO A			
HAZARDOUS POLYMERIZATION	1			_					
		WILL NOT OC	CUR		X	<u> </u>			
			2576.75						
		SE	CTION	VII SI	DILL	OR LEAK PROCE	August 1		
STEPS TO BE TAKEN I	N CASE	And the second second	The second of the second		4 10 10 10 10 10 10 10 10 10 10 10 10 10		or soak up with		
ah aa:			7 11						
SUBOT	,perr	T materi	at u	3111R	ртс	per procee	tive equipment.		
WASTE DISPOSAL MET	THOD			· ·			7-13 40		
			• •				d statutes relative to		
			R	<u>esidu</u>	<u>ιе 1</u>	from evapor	ated solvent can be		
land	fil	led.							
		centio)	a viii	eneri	AT I	ronechtene	Zalat Maria Charles San		
RESPIRATORY PROTEC	TION (	4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 -	4	The Carte	as, sector.				
		AL EXHAUST		Organ	iic	vapor type	SPECIAL		
VENTILATION		HANICAL (Gene	nera II			9	OTHER		
PROTECTIVE GLOVES		· · · · · · · · · · · · · · · · · · ·	<u> X</u>			EYE PROTECTION			
		Rubber c				<u> </u>	Safety glasses		
OTHER PROTECTIVE E	other protective equipment As required by your company								
	*****		EL ATT	V IV	Ane	MMENNEW MAN			
PRECAUTIONS TO BE	TAVEN		755 A		***				
PRECACTIONS TO DE		IN HARDEN.	AND			Same as for	any flammable		
product. OTHER PRECAUTIONS									
UI HEN FREGACIO	<u> </u>					·			
<b>.</b>				•					